

Parameter Description:

P01: Backlight brightness adjustment (1 darkest, 3 brightest).

P02: Speed and mileage unit setting (0 km, 1 mile).

P03: Voltage level setting.

P04: Instrument auto shutdown time setting (1-60 minutes, 0 means no hibernation).

P05: Gear setting (3, 5 gears).

P06: Wheel diameter setting, minimum adjustment unit is 0.1 inch.

P07: Magnet number setting, 1-99 (if it is a gear motor, the reduction ratio needs to be multiplied by the number of magnets).

P08: E-bike speed limit setting, in kilometres.

P09: Zero start/non-zero start setting (0 is zero start, 1 is non-zero start).

P10: Drive mode setting (0 power drive, 1 electric drive, 2 power drive, electric drive coexist).

P11: Boost sensitivity setting (1-24).

P12: Starting torque setting (0 weakest, 5 strongest).

P13: Power disc magnet type setting (5, 8, 12).

P14: Controller current limit setting (controller support required).

P15: Controller undervoltage value

P16: ODO clear setting/restore factory setting. Press and hold up key for 10 seconds to clear ODO. press and hold down key for 10 seconds to restore factory settings.

P17: Cruise control. 0: Disable cruise, 1: Enable cruise.

P18: Display speed ratio adjustment range: 50%~150%.

P19: 0 gear setting. 0: include 0, 1: do not include 0.